


Step 2: Pulling the needed Channel information out of the Cleaned CADD Drawing in GIS  
Greg Dreaper

Converting CADD Boundary

1. Start ArcGIS, from the main menu Click VIEW and select DATA FRAME PROPERTIES. From the COORDINATE SYSTEM tab, select the coordinate system of the Master CADD drawing, and hit OK.
2. Then opening the Master CADD drawing; bring in the polygon version of the Master CADD drawing.



2. Right Click on the Master CADD layer, highlight DATA, and select EXPORT DATA. From the Export Data dialog box, select "Use the same Coordinate System as the Data Frame," and select a file name and location. Repeat steps 1-2 for the polyline layer. (Note: When exporting the polyline, be sure that it is only stations and centerlines are all that is exported. Do not include the boundary polylines.)